

Electric Welding Display

18" square finished display surface. All metal should be $\frac{1}{4}$ " thick metal; 6" long welds; 2" wide flat bar; mounted and labeled.

1. Butt Joint - Single Pass
2. Butt Joint - Multiple Pass
3. Lap Joint
4. Tee Joint
5. Corner Joint
6. Outside Corner weld